

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"4367866".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 08:46
L2	23136	(melting adj furnace)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 08:47
L3	45	2 and ((break or breaking) adj out)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 08:47
L4	286	373/155.ccls. or 432/157.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 08:53

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1980	ohmic adj resistor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 09:37
L2	263	1 and (monitor or monitoring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 09:38
L3	80	2 and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 09:38

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1980	ohmic adj resistor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 09:28
L2	276	1 and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/03/29 09:33
L3	3	1 and (breakout or (break adj out))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 09:34
L4	592	resistor and (breakout or (break adj out))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 09:34

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	13249	(break adj out) or breakout	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 09:20
L2	1888	1 and (warning or alarm or indicator)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 09:21
L3	61	2 and (furnace or crucible)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/03/29 09:21